



## INSPECTION REPORT

Job # 9000 - 18th March 2020

This Pre-Purchase report has been especially prepared for:

**Janine Smith**

### Vehicle Description

| AUDI Q7             |                   | Rating System |           |   |
|---------------------|-------------------|---------------|-----------|---|
| VIN                 | 1C4RJFEG9CC168476 | ★★★★★         | Great     | Like new, well maintained no repairs required   |
| Compliance Date     | 18/1/12           |               |           |   |
| Odometer Reading    | 98261             |               |           |   |
| Registration Number | 4UDIQ7            | ★★★★☆         | Good      | No detectable defect, wear consistent with age and KM   |
| Registration Expiry | 21/2/20           | ★★★☆☆         | Fair      | Will require maintenance or repair in the next 3-6 months   |
|                     |                   | ★★☆☆☆         | Poor      | Some problems require immediate repair or maintenance   |
|                     |                   | ★☆☆☆☆         | N/A or NC | Vehicle does not have this item/not checked potential defect observed -item needs further investigation |

### Overall Rating ★★★★★

#### Overall Comments – Summary of Vehicle Condition

Overall vehicle isn't that bad, does have minor marks on interior and exterior, does need somethings looked at and replaced as I have previously mentioned in the report.

Will contact in regards to report about 10minutes after I have sent just so you can have a read through it first. Overall 3/5





## Interior Overall Rating ★★★★★

|   |                              |
|---|------------------------------|
| ★★★★★   | <b>Seats</b>                 |
| <b>Seats Notes</b><br>Some minor marks on drivers seat base fabric, all other seats okay, all electrics on front seats all operational and working                                    |                              |
| ★★★★★   | <b>Seat Belts</b>            |
| <b>Seats Belts Notes</b><br>Inspected and tested all seat belts, no frays or rips, all locking mechanisms working as they should on each seat belt                                    |                              |
| ★★★★★   | <b>Rear Window Demister</b>  |
| <b>Rear Window Demister Notes</b><br>Operational when tested  |                              |
| ★★★★★   | <b>Front Window Demister</b> |
| <b>Front Window Demister Notes</b><br>Operational when tested   |                              |
| ★★★★★   | <b>Heater System</b>         |
| <b>Heater System Notes</b><br>Operational when tested   |                              |
| ★★★★★   | <b>Horn</b>                  |
| <b>Horn Notes</b><br>Fully operational  |                              |
| ★★★★★   | <b>Window Operations</b>     |
| <b>Window Operations Notes</b><br>All windows fully operational from drivers door main switch and each switch at other doors, Auto up and down function also working on front windows |                              |
| ★★★★★   | <b>All Interior Lights</b>   |
| <b>All Interior Lights Notes</b><br>All interior light operational  |                              |

### Interior Visual Details







|   |                                |
|---|--------------------------------|
| ★★★★★   | <b>Trims</b>                   |
| <b>Trims Notes</b><br>Interior trims do have some minor scuff marks on the plastics, nothing major, marks may be able to come out if cleaned and detailed |                                |
| ★★★★★   | <b>Radio</b>                   |
| <b>Radio Notes</b><br>Tested each function of radio unit, all functions working all okay  |                                |
| ★★★★★   | <b>Air-conditioning System</b> |
| <b>Air-conditioning Notes</b><br>Tested all okay  |                                |
| ★★★★★   | <b>Windscreen Wipers</b>       |
| <b>Windscreen Wipers Notes</b><br>Tested all okay   |                                |
| ★★★★★   | <b>Windscreen Washers</b>      |
| <b>Windscreen Washers Notes</b><br>Washers operational and spray in correct spots on windscreen   |                                |
| ★★★★★   | <b>Remote Central Locking</b>  |
| <b>Remote Central Locking Notes</b><br>Tested both keys, one key tested all okay, other key not operational   |                                |
| ★★★★★   | <b>Locking</b>                 |
| <b>Locking Notes</b><br>Locking of all doors tested all okay  |                                |
| ★★★★★   | <b>Lights Operation</b>        |
| <b>Lights Operation Notes</b><br>Vehicles high and low beam headlights tested and inspected all okay  |                                |
| ★★★★★   | <b>Warning Lights</b>          |
| <b>Warning Lights Notes</b><br>No engine warning lights evident, However messages on dash for oil change due and key remote battery low                   |                                |





**Overall Interior Comments**

Everything tested and checked in this section all operational besides one key that does not lock or unlock vehicle, noted some trims do have minor scuff marks, good detail should be able to remove marks





## Overall Exterior Rating ★★★★★

|  |                                  |
|--|----------------------------------|
| ★★★★★  | <b>Body Panels</b>               |
| <b>Body Panels Notes</b><br>Vehicle was dirty when inspected.<br>Rear bumper has damage left hand side near fog light and lower plastic section near centre of rear bumper,<br>Small dent on right hand front quarter pannel just above body line.<br>Small dint right hand rear quarter near rear door on body line |                                  |
| ★★★★★  | <b>Sunroof &amp; Convertible</b> |
| <b>Sunroof Convertible Notes</b><br>NA   |                                  |
| ★★★★★  | <b>Rear Suspension</b>           |
| <b>Rear suspension Notes</b><br>Inspected rear suspension of vehicle, have found left hand differential bush starting to split, will require replacing soon  |                                  |
| ★★★★★  | <b>Rear Brakes</b>               |
| <b>Rear Brakes Notes</b><br>Inspected rear brakes all okay, approximately 4mm lining left on rear brakes   |                                  |
| ★★★★★  | <b>Rear Rotors</b>               |
| <b>Rear Rotors Notes</b><br>No abnormal wearing or marks all okay  |                                  |
| ★★★★★  | <b>Front Suspension</b>          |
| <b>Front Suspension Notes</b><br>Inspected front suspension, all okay  |                                  |
| ★★★★★  | <b>Front Brakes</b>              |
| <b>Front Brakes Notes</b><br>Inspected front brakes, approximately 6mm brake pad lining left, all okay   |                                  |
| ★★★★★  | <b>Front Rotors</b>              |
| <b>Front Rotors Notes</b>  |                                  |

### Exterior Visual Details







|  |                                  |
|--|----------------------------------|
| No abnormal markings or wearing all okay   |                                  |
| ★★★★☆  | <b>Tyres &amp; Spare Tyre</b>    |
| <b>Tyres Notes</b><br>3 tyres are on the wear indicator which means they are at 1.5mm or less, for tyres to be legal they have to have 1.6mm or more to pass a rwc. Have also noticed tyres have age cracks in the tread which is another indication they need to be replaced.<br>These tyres are also 6 years old which in my opinion is to old and should be replaced regardless |                                  |
| ★★★★☆  | <b>Side and Review Mirrors</b>   |
| <b>Mirrors Notes</b><br>Electric mirrors both tested fully operational all okay  |                                  |
| ★★★★☆  | <b>Exterior Lighting Systems</b> |
| <b>Exterior Lighting Systems Notes</b><br>Inspected exterior lighting system all okay  |                                  |
| ★★★★☆  | <b>Transmission</b>              |
| <b>Transmission Notes</b><br>Selected gears all okay, no abnormal or rough gear shifting all okay,<br>Did however take the vehicle as it was due to be in the workshop to have a oil cooler replaced   |                                  |
| ★★★★☆  | <b>Drive Shafts</b>              |
| <b>Drive Shafts Notes</b><br>Inspected driveshafts and uni joints all okay   |                                  |
| ★★★★☆  | <b>Tail Shafts</b>               |
| <b>Tail Shafts Notes</b><br>Inspected cv shafts all okay, no abnormal noises   |                                  |
| ★★★★☆  | <b>Steering Components</b>       |
| <b>Steering components Notes</b><br>Inspected steering components of vehicle, all okay   |                                  |
| ★★★★☆  | <b>Exhaust</b>                   |





## Exhaust Notes

Inspected exhaust system all okay, no leaks,  
all mounts all okay

## Overall Exterior Comments

Please note in photo under vehicle, puddle on ground is just water from vehicles air conditioning







## Engine Bay Overall Rating ★★★★★

|   |                                  |
|---|----------------------------------|
| ★★★★★   | <b>Fluid Leaks</b>               |
| <b>Fluid Leaks Notes</b><br>No fluid leaks evident when inspected                                       |                                  |
| ★★★★  | <b>Fluid Levels</b>              |
| <b>Fluid Levels Notes</b><br>Inspected all fluids al okay   |                                  |
| ★★★★★   | <b>Pipes and Hoses</b>           |
| <b>Pipes and Hoses Notes</b><br>Inspected pipes and hoses all okay, no signs of premature deterioration |                                  |
| ★★★★★   | <b>Fuel System</b>               |
| <b>Fuel System Notes</b><br>Inspected and tested fuel system all okay, no leaks evident                 |                                  |
| ★★★★★   | <b>Cooling system</b>            |
| <b>Cooling system Notes</b><br>Tested cooling system, system pressurises all okay and does not leak     |                                  |
| ★★★★★   | <b>Braking System</b>            |
| <b>Braking System Notes</b><br>Tested all okay  |                                  |
| ★★★★★   | <b>Brake Moisture</b>            |
| <b>Brake Moisture Test Notes</b><br>Tested fluid all okay   |                                  |
| ★★★★★   | <b>Timing Belt and Chain</b>     |
| <b>Timing Belt and Chain Notes</b><br>No abnormal noises from timing chain area all okay                |                                  |
| ★★★★★   | <b>Drive Belts &amp; Pulleys</b> |
| <b>Drive Belts &amp; Pulleys Notes</b><br>Inspected all okay  |                                  |

### Engine Bay Visual Details








|  |                             |  |
|--|-----------------------------|--|
| <div>★★★★★</div>   | Mountings                   |  |
| <div>Mountings Notes</div> <div>Inspected engine and gearbox mountings all okay</div>                                      |                             |  |
| <div>★★★★★</div>   | Ignition System             |  |
| <div>Ignition System Notes</div> <div>Tested ignition system all okay</div>  |                             |  |
| <div>★★★★★</div>   | Battery and Charging System |  |
| <div>Battery and Charging System Notes</div> <div>Tested battery all okay</div> <div>Tested charging system all okay</div> |                             |  |

## Engine Bay Comments

Everything checked in this section all okay, vehicle is getting a new oil cooler fitted by the workshop next door later today



## Wheels Brakes Overall Rating

|   |                |  |
|---|----------------|--|
| ★★★★★   | Wheel Bearings | <h3>Wheels and Brakes Visual Details</h3>  |
| <b>Wheel Bearings Notes</b><br>No abnormal noises or movement from bearings |                |  |
| ★★★★★   | Parking Brake  |  |
| <b>Parking Brake Notes</b><br>Holds vehicle                                 |                |  |

### Wheels and Brakes Comments

As outlined in second photo of the tyres you can see the age cracked i was talking about





## Road Test Overall Rating ★★★★★

|   |                                  |                          |
|---|----------------------------------|--------------------------|
| ★★★★★☆☆   | Starting & Idle                  | Road Test Visual Details |
| <b>Starting and Idle Notes</b><br>Starting and idling perfect all okay  |                                  |                          |
| ★★★★★☆☆   | Exhaust, Smoke, Emissions        |                          |
| <b>Exhaust Smoke Emmissions Notes</b><br>Tested emissions of vehicle all okay   |                                  |                          |
| ★★★☆☆☆☆   | Clutch                           |                          |
| <b>Clutch Notes</b><br>NA   |                                  |                          |
| ★★★★★☆☆   | Gauges and Speedo                |                          |
| <b>Gauges Speedo Notes</b><br>All operational and in manufacturing specifications   |                                  |                          |
| ★★★☆☆☆☆   | Cruise Control                   |                          |
| <b>Cruise Control Notes</b><br>Tested all okay  |                                  |                          |
| ★★★☆☆☆☆   | Owner's Manual Service Intervals |                          |
| <b>Owner's Manual Service Intervals Notes</b><br>Only owners manual located in vehicle, so unknown history of servicing for this vehicle in the passed, would 110% get the vehicle serviced before picking vehicle up and making sure a invoice of the service is provided to confirm it was done |                                  |                          |
| ★★★★★☆☆   | Engine Noise                     |                          |
| <b>Engine Noise Notes</b><br>No abnormal engine noise all okay  |                                  |                          |
| ★★★★★☆☆   | Gear Box & Differential          |                          |
| <b>Gear Box Differential Notes</b><br>Tested all okay, no abnormal noises or vibrations when driven   |                                  |                          |
| ★★★★★☆☆   | Steering & Suspension            |                          |



|   |                        |  |
|---|------------------------|--|
| <b>Steering Suspension Notes</b><br>All okay when driven, no noises or vibrations |                        |  |
| ★★★★★   | <b>Brake Operation</b> |  |
| <b>Brake Operation Notes</b><br>Tested all okay, brakes stop vehicle efficiently  |                        |  |
| ★★★★  | <b>4 Wheel Drive</b>   |  |
| <b>4 Wheel Drive Notes</b><br>Tested, enagages 4wd all okay                       |                        |  |

## Road Test Comments

Test drove vehicle, went really well, no issues had, very happy with the way vehicle drove





## IMPORTANT NOTES AND DISCLAIMERS

This inspection can only take into account the visible condition and the operation of the vehicle at the time of inspection, ASAP Roadworthy or the inspector will not be responsible for any defects discovered which were not visually apparent during the inspection. The inspection will cover the vehicles exterior, interior, engine compartment, tyres and wheels, breaks, underbody and a road test where possible. Only items on the repurchase inspection checklist are assessed along with any additions requested by you. The inspection will specifically not cover the items set out below. no removal of parts and components is undertaken during the inspection process. Inspectors may not move items such as baby seats or seat covers during inspection. During inspection the engine may not be tested through the full operating temperature range as a result, issue that only become apparent when engine is cold may not be detected if the engines presented hot. If a vehicle is only equipped with a part time 4WD system, and not designed full time 4WD, it may not be driven 4WD during inspection. You acknowledge that while ASAP Roadworthy inspection inspectors use accepted methods of fault detection, these methods will not necessarily identify all faults with a vehicle. you should consider the age and condition of the vehicle at the time of inspection and any report should be reviewed in this context. vehicles are only road tested to speed limit in local area.

The report provided by ASAP Roadworthy to you is only current at the time it is issued, it is a buyer's responsibility to conduct visual inspection of the vehicle at the point of sale as ASAP Roadworthy can only advise on the condition of the vehicle at the time of inspection. The report is not a roadworthy certificate and cannot be used as roadworthy. You acknowledge that ASAP Roadworthy inspect does not check manufacturer recall notices and you should check the vehicle is not subject to recall notice

ASAP Roadworthy will not be responsible for the terms of any transactions between persons in relation to any vehicle inspected by ASAP Roadworthy or for resolving dispute between any persons regarding transaction.

Subject to all applicable laws, ASAP Roadworthy does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the report or the fitness of the information contained in the report for any purpose intended by you. To the full extent permitted by the law ASAP Roadworthy will only be liable to you (I) perusing to any guarantee, right or contractual terms that arises, is created or so implied by operation of the law and that cannot be excluded PROVIDED THAT to the full extent permitted by law, any such liability of ASAP Roadworthy is limited at ASAP Roadworthy option (a) placing or repairing the relevant goods (B) supplying goods equivalent to the relevant goods (C) supplying the relevant services again (d) paying the costs of such replacement, repairs or supply subject to subclass (g) below or (ii) your claim arises from or in connection with any deliberate breach of these terms and conditions or fraud by ASAP Roadworthy.

Except to the extent that liability cannot be excluded, ASAP Roadworthy will not be liable to you for claims arising out of or in connection with your access and use of this report whether arising in contract, tort (including negligence) indemnity, strict liability, breach of warranty or the full extent permitted by law, ASAP Roadworthy will not be liable to you for loss of use, production, profit, revenue, business, data, contractor anticipated savings or delay or for any financial costs or increase in operating costs or any economic loss for indirect or consequential damage.

ASAP Roadworthy does not check the following items:

- ☐ Brake function and lining material, brake drums, limited to what is immediately visible
- ☐ Evidence of brake fluid contamination
- ☐ Anti-lock braking system (ABS) mechanics
- ☐ Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- ☐ Reason for oil leaks
- ☐ Oil pump strainer to assess sludge build up
- ☐ Wheel cylinders
- ☐ Standard to which repairs or service history have been completed
- ☐ Engine cylinder compression
- ☐ Engine mountings
- ☐ Odometer and camshaft belt, drive belt and timing belt
- ☐ Estimated expiry of exhaust system, clutch, dual mass flywheels
- ☐ Functionality of audio-visual or entertainment system including CD,
- ☐ Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- ☐ Degree of gas emissions
- ☐ Catalytic converters
- ☐ Additional accessories included as a result of owner's modifications
- ☐ Mechanical switching of wipers and lights
- ☐ LPG systems
- ☐ Air conditioning efficiency
- ☐ Vehicle electrics and electronics
- ☐ Transmission mechanics
- ☐ Water pump/fan
- ☐ Body water leaks or reason for leaks
- ☐ Status of habitation areas of motorhomes or caravans
- ☐ Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- ☐ Technical systems